

## **ERRATA Note**

### **RE: phyCORE-167/ST10 HS/E Single Board Computer Module with CS8900A Ethernet Controller**

Dear customer,

this errata note affects all shipments prior to October 07, 2002.

Please note the following MAC address programming errors on all phyCORE-167/ST10 HS/E Single Board Computers (order code PCM-018-xxE) shipped prior to October 7, 2002:

The upper- and lower-bytes in the MAC address were erroneously interchanged. For example, the actual internal MAC address as displayed via an ARP-command (arp -a IP-Number) would be "**50-00-14-c2-FF-40**" if the MAC-Address identifier label on a module indicates "**00-50-c2-14-40-FF**".

The *MAC-Edit* software utility enables reprogramming of the MAC address. Please reprogram your modules so that the internal MAC address is identical to the applicable 12-character value on the identifier label.

Instructions on how to use the *MAC-Edit* utility are also attached.

For additional information contact PHYTEC.

**Europe:** 08000PHYTEC / 08000749832

**America:** 1-800-278-9913